

Figure 1 Rocker arm assembly for 1998-2002 Chrysler 3.2L and 3.5L engines. Noise complaints may be due to the associated movement between the exhaust swivel pad, retainer and rocker arm.




Figure 2 Rocker arm and stud location on 1998-2002 Chrysler 3.2L and 3.5L engines.