



Figure 1 2001-2004 GM 6.6L diesel injectors may leak, allowing coolant into the combustion chamber if the injector sleeve seal is dirty or damaged.